

## MAJOR COMPONENT

### Component Status

**Hierarchy** : [Equipment: (1/2848) BD-4012]  
**Additional Filters** : [Task Type: (1/13) CC - Component Change Out] [Component  
**Analyse By** : Equipment

Component	Part No	R	Serial Number	Current		
				Usage	Life Used	UOM
<b>Machine: BD-4012</b>						
1000.0.CC.0 ENGINE				18,079	18,079	Eng - Hrs
3030.0.CC.0 TRANSMISSION				18,079	18,079	Eng - Hrs
3101.0.CC.0 TORQUE CONVERTER				18,079	18,079	Eng - Hrs
4050.LT.CC.0 FINAL DRIVE				18,079	2,699	Eng - Hrs
4050.RI.CC.0 FINAL DRIVE				18,079	2,699	Eng - Hrs
5102.LT.CC.0 LIFT/HOIST CYLINDER			HYC-130	18,079	3,293	Eng - Hrs
5102.RI.CC.0 LIFT/HOIST CYLINDER			HYC-131	18,079	3,293	Eng - Hrs
5104.RI.CC.0 TILT CYLINDER				18,079	18,079	Eng - Hrs
5352.0.CC.0 RIPPER LIFT CYLINDER				18,079	18,079	Eng - Hrs
5354.0.CC.0 RIPPER PIN PULL CYLINDER				18,079	18,079	Eng - Hrs

## UNDERCARRIAGE

### Component Status

**Hierarchy** : [Equipment: (1/2848) BD-4012]  
**Additional Filters** : [Task Type: (1/13) CC - Component Change Out] [Component  
**Analyse By** : Equipment









Component	Part No	R	Serial Number	Current		
				Usage	Life Used	UOM
<b>Machine: BD-4012</b>						
4155.LT.CC.0 SPROCKET SEGMENT				18,079	53	Eng - Hrs
4155.RI.CC.0 SPROCKET SEGMENT				18,079	53	Eng - Hrs
4157.LT.CC.0 TRACK ADJUSTER				18,079	6,113	Eng - Hrs
4157.RI.CC.0 TRACK ADJUSTER				18,079	6,113	Eng - Hrs
4159.LF.CC.0 IDLER WHEEL				18,079	53	Eng - Hrs
4159.LR.CC.0 IDLER WHEEL				18,079	53	Eng - Hrs
4159.RF.CC.0 IDLER WHEEL				18,079	53	Eng - Hrs
4159.RR.CC.0 IDLER WHEEL				18,079	53	Eng - Hrs
4169.LT.CC.0 TRACK LINK ASSEMBLY (SEALED & LUBRICATED)				18,079	53	Eng - Hrs
4169.RI.CC.0 TRACK LINK ASSEMBLY (SEALED & LUBRICATED)				18,079	53	Eng - Hrs
4180.LT.CC.0 TRACK ROLLER				18,079	53	Eng - Hrs
4180.RI.CC.0 TRACK ROLLER				18,079	53	Eng - Hrs

PT. Pacific Firtrack  
Indonesia

CUSTOMER NAME	PT. Madhani Talalah Nusantara
LOCATION	WESTPIT
INSPECTION DATE *)	5-Sep-2022

EQUIP. MODEL	D6R
SERIAL NUMBER	
EQUIP. NUMBER	BD 4012
SMR *)	17715
HOURS / WEEK *)	140
INSPECTED BY	Yudha,Zaqy,Luky

This report was developed by PAFINDO  
and valid for  
D6R only

COMPONENT Undercarriage	Left Side													Right Side												
	Tools	Brand	STD	LMT	HM Install	Actual	Worn%	Life Time	Replacement 100%		Replacement 120%		Tools	Brand	STD	LMT	HM Install	Actual	Worn%	Life Time	Replacement 100%		Replacement 120%			
									HM	Date	HM	Date									HM	Date	HM	Date		
 <b>LINK HEIGHT</b>	Depth	Berco	132.0	118.5	15649	127.0	37%	2066	19044	44875.43922	19723	14-Dec-2022	Depth	Berco	132.0	118.5	15649	127.0	37%	2066	19044	10-Nov-2022	19723	14-Dec-2022		
 <b>LINK PITCH</b>	Tape	Berco	813.0	825.5	15649	820.0	56%	2066	18410	9-Oct-2022	18962	6-Nov-2022	Tape	Berco	813.0	825.5	15649	818.0	40%	2066	18916	4-Nov-2022	19569	6-Dec-2022		
 <b>BUSHING EXT</b>	Caliper	Berco	72.6	59.4	15649	68.0	35%	2066	19149	15-Nov-2022	19849	20-Dec-2022	Caliper	Berco	72.6	59.4	15649	68.0	35%	2066	19149	15-Nov-2022	19849	20-Dec-2022		
 <b>SHOE GROUSER</b>	Depth	Berco	75.0	38.0	15649	53	59%	2066	18328	5-Oct-2022	18864	1-Nov-2022	Depth	Berco	75.0	38.0	15649	54	57%	2066	18391	8-Oct-2022	18940	5-Nov-2022		
 <b>FRONT IDLER</b>	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023		
	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023	Depth	Berco	24.0	43.0	16883	25.5	8%	832	19844	20-Dec-2022	20436	19-Jan-2023		
 <b>CARRIER ROLLER</b>	Caliper	Berco	199.0	158.5	1	180	47%	17714	25863	17-Oct-2023	31036	2-Jul-2024	Caliper	Berco	199.0	158.5	11966	MISS	####	5749						
 <b>Track roller</b>	S	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023	
	D	Depth	Berco	15.0	35.5	11966	22	34%	5749	21804	28-Mar-2023	23772	4-Jul-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	S	Depth	CAT	15.0	35.5	11966	23	39%	5749	21169	24-Feb-2023	23009	27-May-2023	Depth	Berco	15.0	35.5	11966	26	54%	5749	19814	18-Dec-2022	21384	7-Mar-2023	
	D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	S	Depth	Berco	15.0	35.5	11966	22	34%	5749	21804	28-Mar-2023	23772	4-Jul-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023	
	S	Depth	CAT	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	26	54%	5749	19814	18-Dec-2022	21384	7-Mar-2023	
		D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023
 <b>SPROCKET</b>	Tape	Berco	225.0	203.0	15380	211	64%	2335	18307	4-Oct-2022	18892	2-Nov-2022	Tape	Berco	225.0	203.0	15380	212	59%	2335	18418	10-Oct-2022	19025	9-Nov-2022		
<b>Track Adjuster</b>	Tape	Genuine	0.0	147.5		78	53%						Tape	Genuine	0.0	147.5		85	58%							

**Comment :**  
 \* C.Roller RH Not installed

Picture Left Side :		Picture Right Side :	
			
			
			
			
			
			